

LEGEND:

H.P. HIGH POINT L.P. LOW POINT







15-25% SLOPES 25-40% SLOPES



>40% SLOPES

- SOIL TYPE DIVIDE

## RECORD OWNERS / APPLICANTS:

RANDALL S. & ELAINE H. HILLER 8 ADAMS STREET LEXINGTON, MASSACHUSETTS 02420 —DEED BOOK 26502, PAGE 3 \* \*DENOTES DOCUMENTS RECORDED AT THE MIDDLESEX SOUTH REGISTRY OF DEEDS.

## NOTES:

- THE SOLE PURPOSE OF THIS PLAN SET IS TO COMPLY WITH SECTION 135-6.9.3 OF THE TOWN OF LEXINGTON ZONING BY LAW.
- THE TOPOGRAPHY, SITE DETAIL & SURFACE IMPROVEMENTS DEPICTED HEREON WERE OBTAINED FROM THE TOWN OF LEXINGTON ONLINE GIS MAPPING.
- 3. THE SUBJECT PROPERTY DEPICTED IS LOCATED WITHIN THE RS ZONING DISTRICT.
- THE SUBJECT PROPERTY IS DEPICTED AS LOT 77A ON THE TOWN OF LEXINGTON ASSESSOR'S MAP 63.
- 5. THIS PLAN DOES NOT SHOW ANY UNRECORDED OR UNWRITTEN EASEMENTS WHICH MAY EXIST.
- THE LOCUS PROPERTY IS LOCATED IN FLOOD ZONE X (UNSHADED), AREAS DETERMINED TO BE OUTSIDE THE 0.2% ANNUAL CHANCE FLOODPLAN, PER FEMA FLOOD INSURANCE RATE MAP NUMBER 25017C043E DATED JUNE 4, 2010.
- 7. THE SOURCE OF NOISE AFFECTING THE SITE AND ABUTTING SITE IS THE TRAFFIC FLOW ALONG ADAMS STREET AND HANCOCK STREET
- 8. VEGETATION CONSISTS OF OPEN LAWN AREA BETWEEN THE MAIN HOUSE AND ADAMS STREET. MATURE SHADE TREES INCLUDING OAKS EXISTS BETWEEN HOUSE AND GARAGE AND TO THE BACK OF THE PROPERTY. SOME LAWN AREA EXISTING BEHIND THE GARAGE.
- 9. NO LEDGE OUTCROP WAS OBSERVED ON THE PROPERTY.

## SOILS INFORMATION:

SOILS INFORMATION DERIVED FROM THE USDA NATURAL RESOURCES CONSERVATION SERVICE SOIL SURVEY OF MIDDLESEX COUNTY, MASSACHUSETTS, URL: http://websoilsurvey.nrcs.usda.gov.

SOIL TYPE	HYDROLOGIC SOIL GROUP	TYPICAL DEPTH TO ESHGW
MERRIMAC-URBAN LAND COMPLEX	GROUP A	MORE THAN 80"
CHARLTON-URBAN LAND-HOLLIS COMPLEX	GROUP A	MORE THAN 80"

## 8 ADAMS STEET



SITE ANALYSIS MAP LOCATED IN LEXINGTON, MASSACHUSETTS (MIDDLESEX COUNTY)

SCALE: 1"= 40'

RANDALL S. & ELAINE H. HILLER DATE: MAY 31, 2016





500 CUMMINGS CENTER, SUITE 5950
BEVERLY, MASSACHUSETTS 01915
TELEPHONE: (978) 299-0447
TELEPHONE: (978) 299-047
WWW.MERIDIANASSOC.COM

SHEET No. 2 OF 4

PROJECT No. 5875